

25X1

2752-67

Copy 5 of 11

25X1

21 December 1967

## MEMORANDUM FOR THE RECORD

SUBJECT: Critique for OXCART Mission Number BX6739

1. Mission critique was conducted in the OSA Control Center at 1400 hours, 20 December 1967.

2. Mission Data:

- a. Mission Number: BX6739  
b. Date Flown: 15 December 1967  
c. Area of Operation: North Vietnam  
d. Mission Success: Successful  
e. Pilot's Name: [REDACTED]  
f. Aircraft Number: 127  
g. Primary or Spare Flown: Primary  
h. Takeoff Time - Planned: 0230Z  
Actual: 0232Z  
i. Landing Time - Planned: 0636Z  
Actual: 0641Z  
j. Time Enroute - Planned: 4+06  
Actual: 4+09  
k. Departure Base: Kadena AB  
l. Landing Base: Kadena AB  
m. Equipment:

(1) Primary: Type I, [REDACTED]  
[REDACTED]

(2) Spare: Same as primary.

25X1

GROUP 1  
Excluded from automatic  
downgrading and  
declassification

25X1

25X1

25X1


2752-67

Page 2

25X1

3. Operations:

- a. Route (INS Plot vs. Planned): Satisfactory.



- b. Mission Generation & Operational Support: Satisfactory

4. Weather:

- a. Forecast vs. Actual:

(1) As briefed.

(2) Comments: Both primary target areas were Cat I. Overall cloud cover from camera on to off points was 15 percent.

- b. Weather Scout Reporting: Satisfactory.

5. Intelligence:

- a. Target Coverage:

(1) 29 of 29 programmed targets covered.

(2) 9 first priority SSM targets of 9 covered.

(3) 24 of 27 first priority NVN COMOR targets covered.

(4) 156 SAM sites, 17 sites occupied, 6 new sites

(5) 15 other priority NVN COMOR targets covered.

(6) Comments: Excellent, virtually clear coverage obtained on all highest interest areas of North Vietnam. Nearly all of high priority SSM search areas were covered with negative results. Valuable new info was secured on a wide variety of targets such as SAM sites, airfields, bridges and communications centers.

- b. Quality of Take: Satisfactory.

(1) Resolution: 16-18" ground resolution; generally good both passes.

25X1

25X1

25X1

2752-67  
Page 3

25X1


(2) Camera Operation: Satisfactory. Possibility of 3-minute delay in changing to new exposure possibly caused by missed programmer contact in tape occurred in bonus area before mission target coverage.

25X1



f. Take Movement:

(1) Photography: Satisfactory.




25X1

6. Materiel:

a. Aircraft General: Satisfactory.

(1) Comments: Left CIT gage inop after 2+30. Gage found defective, replaced and checked ok.

b. Aircraft Systems: Satisfactory.



25X1

25X1



25X1

25X1

2752-67  
Page 4

25X1

[Redacted]

25X1

7. Communications:

a. Message Traffic: Satisfactory

[Redacted]

25X1

8. Significant Actions Taken:

An airborne spare with a 20-minute second window timing was used on this mission. Timing and refueling tactics have been approved by SAC and BLACK SHIELD OPLAN changed accordingly.

9. Outstanding Actions Required:

a. Deputy for Operations asked that [Redacted] be congratulated on productivity of BX6739 and BX 6740. (Intelligence Division, OSA).

25X1

[Redacted]

25X1

*for*

Deputy for Operations, OSA

25X1

OXC/O/OSA [Redacted]

Distribution:

- #1 - D/SA
- #2 - D/O/OSA
- #3 - D/M/OSA
- #4 - D/R&D/OSA
- #5 - OXC/OSA
- #6 - INTEL/OSA
- #7 - WEA/OSA
- #8 - COMMO/OSA
- #9 - ADP/OSA
- #10 - RB/OSA
- #11 - Chrono

25X1

25X1

TOP SECRET

[Redacted]

25X1